

**Changes to Quality Assurance and Certification Test XML Schema
Version 1.0**

The purpose of this document is to list the changes that were made to the Quality Assurance and Certification Test XML Schema for Version 1.0.

- For the following elements in `OnlineOfflineCalibrationData`, the validation type was changed from "ReferenceValueType" to "CalibrationValueType":
 - `OnlineZeroReferenceValue`
 - `OnlineUpscaleReferenceValue`
 - `OfflineZeroReferenceValue`
 - `OfflineUpscaleReferenceValue`

This was done to support reported numbers that had up to three decimal places and 13 total digits.